



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Address:

Client ID:

Alt. Client ID: 16016SW-0851

AGENCY INFORMATION

Agency: SWHRA

Agency Phone: (731) 989-5111

Address: 1574 White AVE
Henderson, TN

Fax:

Email Address:

Agency Contact: Murley, Rickey

Work Phone:

Cell Phone:

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-425-2492

Client Name:

Work Order (Bid Form)

DOE Weatherization Assistant

Client ID:

Work Order Name:

Version 8.5.0

Alt. Client ID: 16016SW-0851

Report Run On: 5/15/2010

Page 1 of 6

Measures

Measure 1 Seal Ducts				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardware	Mastic duct boots	Each	1					
2	Labor	Labor	Hour						
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Client Name:

Client ID:

Alt. Client ID: 16016SW-0851

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/15/2010

DOE Weatherization Assistant

Version 8.5.0

Page 2 of 6

Measure 2 Infiltration Redctn				Components			Inspected		
Comment									
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardware	Seal crown molding through-out the house	Each	1					
2	Labor	Labor	Hour						
3	Construction Materials/Hardware	Seal pipes under 2 bathroom vanities, Seal water heater vent, Seal pipes under kitchen sink	Each	1					
4	Labor	Labor	Hour						
5	Construction Materials/Hardware	Reseal exhaust vent over cook stove Seal door to sunken den from dinning room	Each	1					
6	Labor	Labor	Hour						
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Client Name:
 Client ID:
 Alt. Client ID: 16016SW-0851

Work Order (Bid Form)
 Work Order Name:
 Report Run On: 5/15/2010

DOE Weatherization Assistant
 Version 8.5.0
 Page 3 of 6

Measure 3 DWH Pipe Insulation				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	Labor	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 4 Attic Ins. R-30				Components A1				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	1992					
2	Labor	Labor	Hour	1992					
3	Miscellaneous Supplies	Install attic access cover. Repair leak around chimney and gas vent on roof before insulating	Each	1					
4	Labor	Labor	Hour						
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Client Name:
 Client ID:
 Alt. Client ID: 16016SW-0851

Work Order (Bid Form)
 Work Order Name:
 Report Run On: 5/15/2010

DOE Weatherization Assistant
 Version 8.5.0
 Page 4 of 6

Measure 5 CO Monitor is Needed				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1					
2	Labor	Labor	Hour	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 6 Smoke Detector is Needed				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke detector	Each	1					
2	Labor	Labor	Hour	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Client Name:

Client ID:

Alt. Client ID: 16016SW-0851

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/15/2010

DOE Weatherization Assistant

Version 8.5.0

Page 5 of 6

**Measure 7 Vapor Barrier Needed
(Basement/Crawlspace)**

Components

Inspected

Comment

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Basement / crawlspace vapor barrier	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Work Order Grand Total:

Grand Total:

Client Name:

Client ID:

Alt. Client ID: 16016SW-0851

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/15/2010

DOE Weatherization Assistant

Version 8.5.0

Page 6 of 6